

A. G. BRAUER SUPPLY COMPANY, STOVE AND RANGE
REPAIRS
316-318 North Third Street
Saint Louis
Saint Louis City
Missouri

HABS MO-1634
MO-1634

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
National Park Service
U.S. Department of the Interior
1849 C Street NW
Washington, DC 20240-0001

HISTORIC AMERICAN BUILDINGS SURVEY

A.G. BRAUER SUPPLY COMPANY, STOVE AND RANGE REPAIRS

HABS MO-1634

Location: 318-316 North Third Street, Saint Louis City, Missouri

Project Information: This structure was part of the Piaget-van Ravenswaay Survey which consists of a number of photographs, primarily of sites and structures in Missouri, taken before 1938 by Alexander Piaget, Paul Piaget, and Charles van Ravenswaay. The Piaget-van Ravenswaay Survey was incorporated into the Historic American Buildings Survey (HABS) collection in 1985 and 1986 by HABS historians Laura Rupp and Deborah Fulton. This photograph remained unidentified until 2008 when it was incorporated into the HABS collection. For more information about the Piaget-van Ravenswaay Survey, see HABS MO-1800.